

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program July 20, 2011

	Mach
D .	d: ANG
Reviewe	d: 1 v

Mine Name: Black Desert Mine	Permit Number: S/023/0088		
Operator Name: Meramining of Utah	Inspection Date: July 13, 2011		
Inspector(s): Wayne Western	Time: 5:10 – 5:40 PM		
Other Participants: Ken Loweder	Mine Status: Active		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond is for \$25,100 and the renewal date is August 31, 2015. The Permittee is current on the permit fees.

The Permittee was building pads for a drill rig that will do exploration drilling. The Permittee wants to bring in drill rigs in the next few weeks to not only drill on in the mine area but also in exploration areas.

The roads are properly maintained.

There were no signs of erosion on the site.

There are no water impoundments on the site.

Inspection Date: July 13, 2011 Page 2 of 4 S/023/0088

Conclusions and Recommendations:

The Division should continue to monitor the site.

Inspector's Signature (YOUR INITIALS):

cc: (OPERATOR)

Jerry Mansfield

O:\M023-Juab\S0230088-BlackDesert\inspections\Insp071320111.doc


John Whiter



Ore pile is behind he pickup truck



Building new pads for drill rigs.



Roads are well maintained.



Equipment on site.